

LLOYD'S REGISTER OF SHIPPING

48 Dalhousie Street

QUEBEC.

June 8th, 1943

A. R. Riddell, Esq.,
MONTREAL, Que.

Dear Sir:

Your letter of June 2nd, 1943, to
hand reference FRIST ENTRY REPORT No. 5819
Minesweepers "FLINT".

This Vessel was rushed to get her away
before the river began to freeze, and was commission-
ed December 18th, 1942.

It was arranged vessel would proceed
to an East Coast Port for "fitting of armament", etc.,
but unfortunately, ice conditions made this impossible
and vessel remained in this Port until opening of
navigation.

During vessel's stay the above work was
done here together with alteration to Crew accom-
modation and deck fittings, hence the reason not
sending the report in January, 1943.


Forecastle side plating should read .28.

Forecastle 27 feet.

Echo sounding device was fitted as done
in Sister Ship.

Yours very truly,

(sgd) C. W. BROWN
Surveyor



© 2020
Lloyd's Register
Foundation

005961-005980-0258

