

1m.12.15.

F.E.

Received by Chief Ship Surveyor 26.1.18

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels 'Henry Ford'

Rpt.

Shul

No. 3034

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

37.12

Depth "d"

12.16

Framing: Table No.

3. page 10

Description

Single angle as approved

Longitudinal No.

5134

Proportions

Length = 10.24

Depth

~~Beck~~ Sheerstrake - 62 of an inch instead of 38 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A.1 (Steel) 'Steam Trawler' as recommended.

1.5K

BK 7½ 4BH. Cam - Lysar ex. Q78'. F19'



© 2021

Lloyd's Register Foundation

005995-006015-0252