

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Wood Aux. S.S. " SANTA ANA". Report Pasajes No. 17

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/22.)

Nature of Survey

When due

This vessel appears to have been built under a roof and in accordance with the approved plans, and to be worthy to be classed

✕ 11 A -, as recommended.

8 years, Table A.

2 years mixed materials.

1 year Roof.

11 A-.

8 & 12 years mat. Roof.

M
23. 6. 19.

It is concluded two thick strakes of ceiling are fitted as shewn on sketch of midship section, but the Surveyors should state if this is so.

du
27/8/19



© 2021

Lloyd's Register
Foundation