

1. B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides
Tanks examined. Also state the amount of deterioration.

CHARACTER,
* for Special Survey.

Not
used
now
expired.

13

Chief Surveyors 15. 8. 21 Received from Chief Surveyors _____
VESSEL'S NAME Steel S.K. Bombay Report Lon No. 83448^a

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/02.)

of Survey Boiler Survey When due 6.21

The boiler Survey of this vessel became due 6.21
In August 1920 the Grimsby Surveyors were
informed by the Manager of Messrs William
Grant & Sons & Messrs Grant Baker Steam
Fishing Co Ltd that the Owners wished
to withdraw the class of all the vessels
belonging to the two companies

It is submitted the class of this vessel
be withdrawn from the Register Book
and (...) inserted.

GRS

Reed
16/8/21

M



© 2021

Lloyd's Register
Foundation

006067-06079-0207