

F.E.

Received by Chief Ship Surveyor 28/3/07

Received from Chief Ship Surveyor

VESSEL'S NAME St. S. Trawler 'Bombay' Rpt. Kul No. 18844

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>9' in lieu of 8'</u>	<u>not required</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Ordinary, increased in size to</u> (viz., ordinary, deep, zed, channel or bulb-angle). <u>Compensate for omission of vertical frames</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A1 (Std) Steam Trawler as recommended.

+ 100 A1 (Std) Steam Trawler
18x

B.H. 8" H B.H. Glen Lloyds A & C Q 67, F17



2021

28/3/07

Lloyd's Register
Foundation

006067-006079-0214

PILLARS, In 'tween Decks, Size and Spacing

" " Hold

Deck, Material and thickness

Forecastle Deck Stringer Plate, brdth & thcknss