

1

Sent to Chief Surveyors 6. 4. 21.

Received from Chief Surveyors

VESSEL'S NAME

s/s. "St George."

Report

Don

No. 84175^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Boiler

When due


4. 21.

The boiler survey of this vessel becomes due this month.

The Owners Superintendent now states, that at the end of the present year the "St George" will be withdrawn from Lloyd's Class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners request.

Withdraw class.
Insert...



© 2020

Lloyd's Register
Foundation

JP [Signature]
6/4/21

006111-006125-0174