

## REPORT OF SURVEY FOR REPAIRS, &amp;c

Date of writing Report 28th Nov. 1941 When handed in at Local Office

Port of SOURABAYA, JAVA.

MAY No 248

No. in Reg. Book. 2476 Survey held at Sourabaya, Drydock Company Date, First Survey and Last Survey 18th Nov. 1941. (No. of Visits 1)

on the Henschel Steel sc. ms. "GENOTA"

TONNAGE— Built at Hamburg By whom Deutsche Wrf AG. B. Fknwrd When 1935 4  
GROSS 7987  
UNDER DK. 7233 Owners N.V. Petroleum Maats. "La Corona" Owners' Address  
NET 4754 Managers Port belonging to WILLEMSTAD

Surveyed Afloat or in Dry Dock? in dock Name of Dock "Soerabaia" Destined Voyage

Cell D B o r D B a feet; u E & B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 6847 Port Sng.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements)

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
+100A1. 11.40.	+LMC.CS. 2.40
ssSba.No.1-40	2.40
Carrying Petro-	DBS. 2.39
leum in bulk.	TS.CL. 2.40
	Oil Eng
	Mchy Aft

In damage cases where the Surveyor has not made a special damage report he is required to state whether he:  
offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

Oil Engines  
Continuous Survey.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition:

Vessel placed in drydock, bottom and rudder cleaned, examined and found in No.1 & No.2  
keelplates many deteriorated rivets; same welded up, further in good condition and recoated.

## SUMMARY OF DAMAGE REPAIRS:—

Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...							
Removed and Faired or Repaired ...							
Faired or Repaired in place ...							

## PRESENT CONDITION OF THE

Decks good	Bulkheads	Engine Room Skylights good	Copper, or Y.M. (State if on Fett.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement	Oil Bunkers good	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of 3 B. 1 S.
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged) no
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Have the Tanks been examined internally? no	Timbers of Frame at openings	Chain Locker
Keelsons	Have the Tanks been tested?	" " at other places	Hawsers & Warps good
Stringers		Stringers, Clamps & Shelves	Standing and Running Rigging
Inner Bottom Plating		Salting (State if examined.)	Sails
Doubling Plates under Sounding Pipes			

## General Observations, Opinion as to Class, Recommendation, &amp;c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without 'fresh record of Survey,'" "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Vessel to remain as classed, with fresh record of survey Sba.11.41.

Survey Fee (per Section 29)	£ 80.00.
Special Damage or Repair Fee (if any) (per Sec. 29)	£
Travelling Expenses (if chargeable)	£ 5.00.
Second Surveyor's Fee (if any)	£

Fees applied for, 28/11/41.

Received by me, 19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

TUE 19 MAY 1942

TUE 15 DEC 1942

TUES. 29 FEB 1944

Lloyd's Register  
FOUNDATION

Is Certificate required? If so, to be sent to Owners' address

006160-006174-0060