

Jan, 10, 38.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

MONTEVIDEO

Report

Bcl.

No. 6808

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage
& Alteration to rudder
(See approved plan attached)

When due

16301
BCL
(5.39)

Subject to some bearing brackets for the drum shaft of
the windlass being renewed, and the drum shaft tested at the
Owner's convenience.

C.B.

H.S.

SRL. delete repair indicated plotting etc

24.4.39
© 2021
Lloyd's Register
Foundation
006175-006188-0180