

COPY.

ALERT
FLEETWOOD

16.5.24.

GAUL CLASS MUST BE EXPUNGED WITH RED LINE FORTHWITH
UNLESS BOILER AND SCREWSHAFT SURVEYS ARE HELD BEFORE VESSEL
PROCEEDS TO SEA WIRE REPLY

COMMITTEE PEN



© 2021

Lloyd's Register
Foundation

006204-006220-0025