

1

24 JAN 1924

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl. S.K. "WOODBURY"

Report Lon. No. 87412

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

The 2nd.s.s.No.1 became due 6,23.

The class is subject to some indented plates being dealt with at the Owners' convenience.

The Grimsby Surveyors now state the Owners wish the class to be withdrawn.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class

Insert ...

© 2021
Lloyd's Register
Foundation
23.1.24