

17 JAN 1924

Sent to Chief Surveyors 15. 1. 24.

Received from Chief Surveyors

VESSEL'S NAME

S. "Storm Centre" Report Don

No. 87374^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw shaft

When due

11. 23.


The examination of the screw shaft became due in 11. 23 & in reply to the usual notice the Owners state that it has never been their practice to require the Society's class with regard to their smaller vessels & in this case they are reluctantly compelled to ask the Committee to withdraw the vessel's class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners request.

Withdraw class.

Insert ...

C.D. JED
15/1/24



© 2021

Lloyd's Register
Foundation