

F.E.

Received by Chief Ship Surveyor 5.7.05

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. Steam Trawler "Viola"Rpt. Hull No. 16955

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>8/16" in lieu of 7/20"</u>	<u>Not required.</u>
Spar Sheerstrake . .	<u>"</u>	<u>"</u>
Description of Framing:— <u>Ordinary 5/16" in lieu of 5/20" thick, and</u> (viz., ordinary, deep, zed, channel or bulb-angle). <u>spaced 1" closer than required.</u>		

The Chain Cables are 7 lbs. less in weight than required by Table 22 in the Rule length of 90 fathoms.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ± 100A1 ("Steel") "Steam Trawler" as recommended.

± 100A1 ("Steel")

Steam Trawler10R.BK 7½" 4BH Can. Plough ABCP Q 65' F 22'

© 2021

C. H. J.
5/7/05
 Lloyd's Register
 Foundation