

H. S. J. "Victoria"

Received from Chief Surveyors

Report

Liv.

No.

79748

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/82.)

No.

7

SURVEY PARTLY HELD.

20


When proposed to be completed

(S. N. 1 became due 2. 16)

Complete Survey: Bunkers to be examined.  
ended 10.19 has been assigned.


J. M.

23. 11. 19.



Surveyors should be requested to state the lengths of  
chain cables now on board.

6/11/19.



© 2021

Lloyd's Register  
Foundation

006204-006220-0261