

1

15
12 FEB 1925

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Hopper barge Ganquil N^o 2

Report

Am

No. SP356A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

Screw shaft

When due

12. 24.

The screw shaft became due for survey in December last.

The Bilbao Surveyors now forward a letter from the Director General de Navegacion Madrid stating that they do not require Lloyd's survey for this or any other vessel belonging to the Spanish Government.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

Withdrawn class
Insert ...

S. J. C. S.
11/2/25.

[Signatures]



© 2020

Lloyd's Register
Foundation