

N.B.—All alterations in the existing records should be
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides
of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,
girders, and of the inner bottom plating, especially in the boiler space.

for Special Survey
Date of last Survey and of
Periodical Surveys.

A - 5.22

Steel Screw Steamer "CHIOS"; No.16577 in the Register Book;
4549 tons gross; Built in 1920 - 6 mo.;

Owners: Greek Government Service of Maritime Transport

Classed: 100 A- LMC 10,20.
5,22

[Handwritten signature]

The Screw Shaft of this vessel became due in
October last, but in a letter, dated 11th ultimo, addressed
to the Society's Surveyors at Piraeus, the Greek Minister of
Marine states that the steamer has been converted into a
repair ship and is now a unit of the Greek Navy, so that the
Society's Classification is no longer required.

In the circumstances the Classing Committee, who
had the case before them on Tuesday, 5th instant, decided to
give instructions for the vessel's character to be withdrawn
from the Society's Register Book and three dots (...) inserted
in lieu thereof, indicating withdrawal of class at Owners'
request.

[Handwritten signature]

7th February, 1924.



© 2020

Lloyd's Register
Foundation

006248-006257-0062

7 insert (100)

Write Down
Pir.

decision

(if assigned
and now ver
s for this pur

32

aff
rit
a

ners.

Rule

&

g &

e R

s