

4 E

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

13 APR 1946

SEEL'S NAME

"DENIS DAVYDON"

Rpt.

Npt.

No. 25098

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey


~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Docking.

The screwshaft of this vessel has not been examined since the vessel was built in 1939.

It was recommended in 11.45 that the screwshaft be drawn for examination at a convenient opportunity. This has not been done.

~~It is submitted the Owners be informed.~~



© 2021

Lloyd's Register  
Foundation

15.4.46