

5m, 6, 14

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Twin S. Merryweather Report *Rm*

No. *87787^a*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Water Tube Boilers

When due

11.23.

The annual survey of Water Tube boilers became due in Nov last.

The Owners now state in reply to inquiry that as the vessel is only employed in Rangoon Harbour for fire salvage purposes they do not consider it necessary to retain her class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

*Withdraw class
Insert ...*

[Signature]
9/5/24

[Signature]

[Signature]



© 2021

Lloyd's Register
Foundation

006332-006342-0135

006332-006342-0136