

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

At S. J. James Pitcher's Rpt. Abu No. 10725

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

34.75

Depth "d"

11.41

Framing: Table No.

3 pages

Description

Single angle, as approved

Longitudinal No.

3996

Proportions

Length

Depth

9.02

~~Deck~~ Sheerstrake

50 in lieu of 34 as required

by the Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A.1. ("Steel") "Steam Trawler" as recommended.

+ 100 A.1. ("Steel") "Steam Trawler"

120

MB = 213 f 21' 13"

BK 7 1/2 3 BH. Cum. Lloyds at 60

© 2021
Lloyd's Register
Foundation

006332-006342-0267