

COPY.

19th April, 1921.

HAMBURG.

pro

541 "SKOGLAND". To remain as classed, and in view of the extent
your inspection, with fresh record of survey 1,21 subject
recommended. Also assigned notation MBS 3,21.

553 "BROCKTOWN". Class re-instated 100A1 and assigned notations
S.No.2-2,21, Lloyd's A&GP and +IMC 3,21. I have to request that
you will state whether it was considered necessary to drill the
well plating, and may add that if this was not so a notation
S.S.No.3 could be assigned if desired by the Owners.
558,63,4. As recommended.

For cert on reply



© 2021

Lloyd's Register
Foundation

006357-006368-0032