

18 APR 1921

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME Steel S.S. "BROCKTOWN" Rpt. Ham. No. 14553

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The class of this vessel was expunged with a red line 12.16, (German Owned).

The Hamburg Surveyors now report that with a view to reinstatement of class the vessel has been examined in dry dock and the requirements of the S.S.No.2 carried out.

The bottom has been cleaned and coated and minor repairs effected.

Damage through collision:- Bulwarks repaired.

It is submitted the vessel appears worthy to have her class reinstated in the Register Book with record of survey 3.21 and notation of S.S.Ham.No.2-21.

*Reinstated  
100 A.1  
3.21 Ham.  
S.S. Ham No. 2.21  
Lloyd's A 161*

*[Signature]*  
14. 4. 21.

The Surveyors should be informed that provided it was not considered necessary to drill the shell plating, notation of S.S. No.3 could be assigned if desired by the Owners.



© 2021

Lloyd's Register Foundation