

S. S. "GOLDENFELS"

As it would appear that some damage repairs
have been carried out on this vessel, it is submitted
that the Hull Survey Report should be returned to the
ordiff Surveyors, and they should be requested to write
the Damage Survey Report separate from the Condition Survey.
They might also be requested to state what they think
will be an adequate fee to charge for the Damage Survey
report.



FR
JM
17. 6. 20.

© 2021

Lloyd's Register
Foundation

006358-006368 - 0061