

S.S. "DUNLETH"

This vessel was recently under survey at Aberdeen for damage by stranding. See Aberdeen Report 12545 September 1920.

The Aberdeen Surveyors reported the vessel as badly damaged and temporary repairs were effected to admit of her proceeding in tow to Amlwch, Anglesey for the purpose of being permanently repaired.

The Liverpool Office subsequently forwarded a letter from Messrs. Thomas & Sons of Almwch stating that it was not their intention to carry out all the work recommended by the Aberdeen Surveyors. They proposed to do what they considered necessary and afterwards invite the Surveyor to inspect the repairs, and if found to his satisfaction to continue the class.

The Surveyors were instructed to point out to the Owners that the Society's Rules require all repairs to hull or machinery in cases of vessels classed with this Society to be carried out under the inspection and to the satisfaction of the Society's Surveyors.

The Liverpool Office now forward copies of further correspondence they have had with Messrs. Thomas & Sons, and it is submitted there is nothing to add to what has already been communicated to the Owners from Liverpool.

The reports on the case should be forwarded to
Liverpool.

RP
CJ
12.10.20.

© 2020 Lloyd's Register Foundation
006401-006406-0061