

S.S. "TOURS"

It is submitted the Cardiff Surveyors should be informed by wire that if the welds of the stern frame appreciably opened out while the frame was being fitted in place, it is considered the stern frame should be returned to the forge and re-welded and carefully examined.

Let N 2/10/19



© 2020

2.12.19.

Lloyd's Register
Foundation

006424-006434-0014