

s.s. "BAUTA" ex "Canadian Sealer".

By withdrawal of class, see correspondence

It is submitted that as this vessel is classed with this Society, the Plymouth Surveyor should be instructed to inform the Master of the requirements of the Society's Rules as regards the survey of repairs as stated in Section 10, Page 11 of the Rules, and he should be instructed to survey the vessel, and to forward a report in the usual manner, detailing the damage repairs which have been effected.

[Signature]
12.1.25

Cable Owners



© 2021

Lloyd's Register
Foundation