

"
S. S. Canadian Sealer"
"

submitted, the Halifax Surveyors he requested
if they are correct in stating that no fuses
d on the main switch board, to the cables
circuits

JWR. 114 15/4/20.

006435-006446-0058