

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S.S. BORDEAUX MARU Rpt. Kob. No. 4186**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 82 Depth "d" 15.92'Framing: Table No. 3 Description Bull angles as approvedLongitudinal No. 33210Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.95}{}$ Awning Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100 A.1. (Steel) Awning Dk. with freeboard," as recommended. The Summer freeboard of 106.6 ins. from centre of disc to top of statutory deck line at Awning deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks. (Stl.) & Awning Dk. (Stl.)
bell D.B. 342' 1234t, DTA 35' 424t, FPT 104t, APT 36t,
F.K. Collision BH to Awning Dk, 5 BH to Upper Dk,
pt. Cen, Lloyds A & C.P., F 33' on Awning Dk