

It is submitted Messrs Frank Bevis Ltd be  
informed the Rotterdam Surveyors have been  
communicated with in respect to the points  
raised in their letter of the 4<sup>th</sup> inst, and  
that from the Surveyors <sup>statements</sup> ~~explanation~~ it does  
not appear there has been any neglect  
on their part in carrying out the Special  
Survey of these vessels.

Messrs Bevis Ltd, should be further  
informed, the Surveyors point out these vessels  
lay for a considerable time alongside other  
lighters in an open harbour & in shallow water  
before being taken over from the Builders,  
and that in their opinion the chafed & wavy  
bridge plating in the case of the "Rocksand",  
may be due to damage sustained whilst  
the vessel was lying afloat in the Harbour.



© 2020  
16.4.13

Lloyd's Register  
Foundation

006489-006504-0053