

House
Upper Deck Beam, at side
When built 10.12.13.

on to **Lloyds Register of British & Foreign Shipping.** from FRANK BEVIS Ltd, 4/8/13. 19

Dumb Hopper Barge "SANDBANK" (Cont.)

Several seams are not fair, which is probably due to structural defects. These are most prominent in the bilge strake of plating.

From the above it appears that there must have been some lack of supervision in the construction of these boats and we shall be glad to receive your remarks thereon.

In the meantime,

We remain, dear Sir,

Yours faithfully,

FRANK BEVIS, LTD.

Frank Bevis
(Manager)

Not: F.P.B.

Exd: *JB*



© 2020

Lloyd's Register
Foundation

0064 2/2

in Holds,

with profile

BULKHEADS.

In Vessel Per Rule

Thickness

Horizontal

Referred to the Chief Ship Surveyor.

FAW

Referred to Mr. S. A. Hill.

Referred to Mr. Mayne.

SEP -5 1913

M
5-9-13

Handwritten signature
(mirrored)

THE VESSEL, NAME OF
REGISTERED AT

...of the ...
...of the ...
...of the ...

...of the ...
...of the ...
...of the ...

(Name) "..." equal to the ...

...of the ...
...of the ...

© 2020 Lloyd's Register Foundation

NAME
Ship Surveyor

Signature of the

Enclosure
to print out &
presented in the

Answer
Name:
Address:

Signature