

LLOYD'S REGISTER OF SHIPPING
17 BATTERY PLACELLOYD'S REGISTER,
LONDON.

REC'D 21 JUN 1920

NEW YORK June 9, 1920.

ANS'D

Dear Mr. Mayne:

With reference to your letter of the 8th ultimo and to Seattle report No. 933 on the steamer "ROBIN GOODFELLOW", I enclose herewith a letter dated the 2d instant received from the Surveyors from which it will be seen that two sets of duplex pumps have been installed and connected for oil lubrication. There is also one oil end piston and rod for lubricating pump on board.

The turbine thrust adjusting bushes are supplied but there are no liners for adjusting blocks.

The above applies in the case of the steamers "ROBIN HOOD", "ROBIN ADAIR" and "ROBIN GRAY".

Yours faithfully,

F. A. Mayne, Esq.,
LONDON.

© 2020

Lloyd's Register
Foundation

