

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 7th July 1941 When handed in at Local Office

Port of PORT NATAL

N. in
Reg. Book.

Survey held at PORT NATAL

Date, First Survey 12th JuneLast Survey 13th June

1941

20618 on the Steel M.V. "BRISBANE MARU"

TONNAGE:-

ROSS 5425

NDER DK 4941

ET 3220

Built at Yokohama

By whom Yokohama Dock Co. Ltd

YEAR MONTH

When 1930 - 5.

Owners Osaka Syosen K.K.

Owners' Address

(if not already recorded in Appendix to Register Book).

Managers Do

Port belonging to Osaka

urveyed Afloat

Name of Dock

Destined Voyage South America

LLD Bord Ba

feet; uE&B

feet; f

feet

al capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

ast Report, No. 11656.

Port Kob.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. Xt for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
+100A1	+LMC GS) 8.39
8.39	6.38.
S.S. OSA. N°2 - 39.	D.B.S 11.40 8.39
with freeboard 11.40	TS (CL) 6.38

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as
printed on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

Interim Certificate

It was reported that whilst the Vessel was at Port Natal on the 12th June 1941, the Harbour Tug "Harry Escombe", struck the rudder.

On examination no damage was found. As a precautionary measure a diver was employed to make an examination of the Rudder and propeller fastenings. His report being satisfactory.

The Steering Engine was tested and found satisfactory.

ARY OF DAMAGE REPAIRS:-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

ENT CONDITION OF THE

	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Fett.)
ing of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
ags	Cement or Asphalt	Oil Bunkers	Boats
& Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
in way of sidelights	Windlass	Hatches	Equipment letter
e Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
adinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
erses	Have Watertight Doors been examined and found efficient?	Treenails	length mean diam. (on board)
s	Have Vent Masters and their Coamings been examined and found efficient?	Breasthooks & Stewson	Rule length size
rs	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
ottom Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
he Tanks been examined internally?		" " at other places	Standing and Running Rigging
he Tanks been tested?		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without 'fresh record of Survey,'" "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This Vessel is eligible in my opinion to remain as classed, subject further examination of the Rudder at the first convenient opportunity.

Survey Fee (per Section 20)	5 : 5 : 0
Special Damage or Repair Fee (if any)	
Travelling Expenses (if chargeable)	11 : 6
Second Surveyor's Fee (if any)	

Fees applied for,
13.6. 10.41
Received by me,
19

T.H. Noël
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

TUE. 9 SEP 1941

TUE. 5 MAY 1942

OMIT CLASS
ON RE-PRINT.

006512-006522-0006

Lloyd's Register
Foundation