

# Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, January 30th, 1929.

Cert. No. 17761

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd, Kobe,

the Open Hearth Steel Forgings or Castings named below ~~was~~ <sup>were</sup> examined and tested at their works on January 17 to 26, 1929 ( 4 visits )

and found to be as far as could be ascertained, sound and free from defect.

One (1) Propeller shaft 16 inches ( black dia )

Examined in black forged condition.

~~Drop tests.~~

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Band 1" x 3/4" x 180°
✓ <u>B 1210 A 1</u>	<u>29.8</u>	<u>35</u>	<u>Good</u>

This shaft is intended for Yokohama Dockyard ships

Nos. 172-4 or 175

and <sup>has</sup> ~~been~~ stamped as follows:-

Fee Yen 40.00

Expenses „ 1.00

B 1210 A 1  
LLOYD'S  
No. 1776  
26-1-29  
L.R.A.W.

A. A. Latt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society.”



172

Lloyd's Register of Shipping

(MEIKAI BUILDING)

35, AKASHI-MACHI,

Kobe, January 30th, 1929.

17767

Cert. No.

This is to Verify that at the request

Messrs. The Kobe Steel Works Ltd. Kobe,

the Open Hearth Steel Forgings or Castings named below were examined and tested at their works on January 17 to 26, 1929 (4 visits)

and found to be as far as could be ascertained, sound and free from defect.

One (1) Propeller shaft 16 inches (black dia)

Examined in black forged condition.

Prop. tested

Test Mark	Tensile Tons/in	Elongation % in 2"	Hard 1" x 3/4" x 180°
H 1210 A 1	29.8	25	Good

This shaft is intended for Yokohama Dockyard ships

and has been stamped as follows:-

LLOYD'S  
No. 1776  
10-26-1-29  
L.R.A.W.

Fee 40.00  
Expenses 1.00

Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:--  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of the Surveyors, other Officers or Agents of the Society."



25/9 26/9 27/9 28/9 29/9 30/9 1/10 2/10 3/10 4/10 5/10 6/10 7/10 8/10 9/10 10/10 11/10 12/10 13/10 14/10 15/10 16/10 17/10 18/10 19/10 20/10 21/10 22/10 23/10