

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, March 15, 1929.

Cert. No. 1886.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd. Kobe.

the Open Hearth Steel ~~Forgings~~ or Castings named below ^{were}_{were} examined and tested at their works on February 21, 26 and March 7, 1929 (3 visits)

and found to be as far as could be ascertained, sound and free from defect. Two (2) propeller bosses examined in rough machined condition

Drop tests: Dropped from a height of 10 feet on to hard ground, then suspended and hammered without indication of defect.

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 3/4", 120°
<u>B2836-2</u>	<u>29.3</u>	<u>33</u>	<u>Good</u>
<u>B2846-1</u>	<u>28.8</u>	<u>32</u>	<u>"</u>

These propeller bosses are intended for Yokohama Dockyard Ship
Nos. 173-174 or 175 and ^{has}_{have} been stamped as follows:-

Fee Yen 30.00
Expenses „ 1.00

B2836-2, B2846-1
LLOYDS
No. 1886
7. 3. 29
L.R. A.W.

Aulatt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society.”

Lloyd's Register of Shipping

(MEIKAI BUILDING)

32, AKASHI-MACHI,

Kobe 15, 1929.

Kobe

Cert. No. 1886.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd. Kobe.

the Open Hearth Steel Forgings or Castings named below were examined and tested at their works on February 21, 22 and March 7, 1929 (3 visits)

and found to be as far as could be ascertained, sound and free from defect. Two (2) propeller bosses examined in rough machined condition

Drop tests: Dropped from a height of 10 feet on to hard ground. then unspurred and hammered without indication of defect.

Test Mark	Tensile Strength in Tons/sq. in.	Elongation % in 8"	Bend 1 1/2 x 3/4" 180°
28846-2	29.8	23	Good
28846-1	28.8	22	"

These propeller bosses are intended for Yokohama Dockyard Ship No. 178-174 of 175 and have been stamped as follows:-

28846-2, 28846-1
LLOYD'S
No. 1886
F. & S.
I.R. & W.

Fee 30.00
Expenses 1.00

Signature to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."

Lloyd's Register
Foundation

000515-000525-0028

25/8. 26/8. 28/8. 30/8. 2/9. 13/9. 14/9. 17/9. 19/9. 25/9. 8/10. 12/10. 15/10. 18/10. 22/10. 23/10.