

mW

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME..... EMPIRE FRIEDA..... REPORT..... Lon. 114984A
No.....

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

at of Survey..... When due.....

Upon enquiry of the appropriate Department at the Admiralty it is learned that it is not desired to continue the classification of this vessel with Lloyd's Register. (See special endorsement 22.5.47).

It is therefore submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
and insert (...)



W.O.T.
© 2020 25.6.47.

Lloyd's Register
Foundation

006564-006572-0091