

nt to Chief Surveyors 4. 7. 17.

5 JUL 1917

Received from Chief Surveyors

VESSEL'S NAME

s/s "Grackle"

Report

Lon.

No.

80031.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement"—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

Screw shaft

When due

1. 17.

The first biennial survey of this vessel's screw shaft became due in January last.

In reply to the usual notice the Owners now write stating that it is not their intention to keep this vessel in class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class.
Insert . . .

M. J. W. D. 9/17/17.
4/4/17.



© 2020

Lloyd's Register
Foundation