

F DISCL

DISCLOSED SECTION
(Received at London Office)
OF SURVEY FOR REPAIRS, &c.

LA No. 4523 NO 24

When handed in at Local Office 19... Port of PORT-OF-SPAIN.
Date, First Survey Last Survey 19

Steel M.S. "DENBYDALE"
at Sleepers By whom Rytkenovs Lb Co. When 1940
Ministry of Shipping Owners' Address
The Admiralty Port belonging to Sleepers

Dock? Name of Dock Destined Voyage
U&B feet; f
tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER. Machinery and Boiler
* for Special Survey. Date of last Survey and of Periodical Surveys. (Including date of N.B., if any).
+100ft 1.41 +LMC1.41

Detail and serial in the terms of the Rules and items remaining to be clearly the cause of Repairs, if any, and, in detail, the nature and Repairs on account of Damage (the cause of which must be stated) causes; and besides being detailed in the body of the report, should be for the replacement of Anchors or Chains is reported the particulars on the back of this form. State also the dates and initials of any letters

Not made a special damage report he is required to state whether he to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?
R RULE, FOR


Y OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fitted or Repaired ...								
Fitted or Repaired in place ...								

ENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
ing of Becks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
ings	Cement or Asphalt	Oil Bunkers	Boats
s & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
le Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
.. in way of sidelights	Windlass	Hatches	Equipment letter
es	Have pumps been examined and found efficient?	Planking	Anchors, No. of
ne Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
tudinals	Have Watertight Doors been examined and found efficient?	Treenails	.. length mean diamr. (on board)
urses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	.. Rule length size
ternally?	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
		.. at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

ations, Opinion as to Class, Recommendation, &c. :-
any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
ple :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Fees applied for, 19...
Received by me, 19...

18 MAR 1941



© 2021
Lloyd's Register
Foundation

006601-006613-0163