

7th April, 1920.

2500,12,19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "MOTO"* Report *Grk.* No. *17635*

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

When due

The intermediate Bulkhead in fore hold has been dispensed with.

* *100 A.1. (steel)*

1 Dk. (steel). "Well Dk"

DTa 42' 228t. Cell DB 224' 633t. FPT 113t. APT 114t.

FK. "Intermediate BH. in fore hold dispensed with" (4 BH's only). Gen. Lloyds A7C.P.

*The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.*

P 27', Q 214', F 31'.

*attS
7-5-20*

*This included the total length of wireline is made up to 100 fathoms by the addition of 15 fathoms
of 12" manilla as approved but the Surveyors should be requested to state if this is not.*

006601- 006613- 0242

006601- 006613- 0243