

Chief Surveyors _____ Received from Chief Surveyors _____
EL'S NAME *St Libra* Rpt. *Std.* No. *25252*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

~~No.~~ **FE. SURVEY PARTLY HELD.**

When proposed to be completed _____

due _____
on of Survey held, &c. _____

*This vessel has just been built at Dundee and
engined at Sunderland.*

*The surveyors at the latter port have forwarded
a first entry machinery report, in which they state that to
complete the L.M.C. survey the Main Boiler safety valves
require to be overhauled and readjusted.*

*It appears that, when the valves were tried
under steam, the accumulation pressure proved to be excessive,
and the Sunderland surveyors arranged with the Engine
makers and the owner's superintendent to complete the survey
on the vessel's arrival at Grimsby. The Grimsby Surveyors were
notified accordingly.*

*The hull fees having been paid, and certificates
requested by the owners, the Grimsby surveyors were ^{asked} requested by
wire to state what had been done. In reply they state that
the Superintendent has been consulted, and informed of the
requirements, but has decided to send the vessel away for one trip,
arrangements have been made to have the matter attended to on her
return. In the meantime the vessel has gone to sea.*

*It is submitted that the Dundee surveyor be informed
that, to complete the machinery survey the Main Boiler safety valves*

idge House
ecastle
ases on Dk
as of Hatc

of "LIBRA"

Continued.

Old Rpt. 2525'2

valve

which proved to be unsatisfactory when tested, require to be overhauled and put in good and safe working conditions.

The vessel has, however, proceeded to sea without this being done, the owner's representative stating that the matter would be attended to on the vessel's return.

They should also be informed that the fee for the special survey of the machinery has not yet been paid.

In these circumstances action as regards the Classification is being deferred.

J.R.A.

(S)

13.5.12



© 2021

Lloyd's Register
Foundation

015524