

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

11th May, 1912.

Gentlemen,

I have to acquaint you that the Society's Surveyors at Sunderland report that in order to complete the first entry machinery survey in the case of the S.S. "LIBRA", the main boiler safety valves require to be overhauled and re-adjusted. They state that this matter is to be attended to on the vessel's arrival at your port, and that they have advised you accordingly.

The first entry certificates in this case are urgently required, and I have to confirm the following telegram which has been sent to you in the matter this morning, viz:-

"New trawler "LIBRA" wire whether safety valves
"put in order as advised you from Sunderland certificates
"urgently required forward reports today if survey
"completed".

I am, Gentlemen,

Your obedient Servant,

The Surveyors,
GRIMSBY.



© 2021
Secretary.

Lloyd's Register
Foundation