

F.E.

Received by Chief Ship Surveyor *18/1/10.*

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl stm. Trawler**"Varanis"*Rpt. *Hull*No. *22074.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

| Items. | Additions (if any) required by Rules, or as approved. | On account of:— |
|---|---|---------------------|
| Main Sheerstrake . . | <i>2 1/16" in lieu of 2 1/20"</i> | <i>not required</i> |
| Spar Sheerstrake . . | <i>✓</i> | <i>✓</i> |
| Description of Framing:— <i>Ordinary framing, increased in depth for omission of reverse frames.</i> (viz., ordinary, deep, zed, channel or bulb-angle). | | |

The 1st Bower Anchor is 10 lbs less than required by the Rules and the 2nd Bower anchor is 18 lbs heavier than required by the Rules, in other respects this vessel appears to have been built in accordance with the

Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A1 ("Steel") "Steam Trawler"** as recommended.

✠ 100 A1 ("Steel") "Steam Trawler"
1 DR.

B.K. 7 1/2" 4 BH. Cem. Lloyd's A.V.C.P. Q 68' RFD 22'

Mr. R.A. 18/1/10



© 2020

Lloyd's Register
Foundation

006641-006653-0301