

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Stl. Sc.K. "OCEAN QUEEN" Rpt. Gms. No. 13699**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey .....

(SS No 3 due 1.18 held on hull)

The 2nd.s.s.No.1 became due 7,23.

The vessel is laid up at Grimsby and the Surveyors recently stated she was in the hands of Messrs. Barclays Bank, and no decision had been arrived at regarding the special survey.

The Surveyors now report the vessel placed in dry dock and the bottom cleaned and coated.

The stem bar was found set over between C. and E. strakes and several topside plates on port and starboard sides more or less indented but, in the Surveyors' opinion, repairs may be carried out at the Owners' convenience.

It is submitted action be deferred.



© 2021

22.11.23.

Lloyd's Register  
Foundation

006680-006693-0333