

250,12,10.

Mabuhay I

F.E.

Received by Chief Ship Surveyor 14/2/11

Received from Chief Ship Surveyor _____

VESSEL'S NAME At St Terrier

Rpt. Sea

No. 24719

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 81.66

Depth "d" 17.66

Framing: Table No. 3 page

Description Bulk angle, 5' less in depth

Longitudinal No. 32604

but compensated by increased thickness

Proportions Length = 10.59
Depth =

BRIDGE Deck Sheerstrake ✓

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100A-1 (Std) as recommended.

+ 100A-1. (Std)

2nd (U. plan - p. 101. 2nd an std)

WB. buu DBa 137 u 324 f173 11946 FPT 1231 APT 1231

FK CBH. Gen. dngs at C.P. PHH, B121 FHI



© 2020

Lloyd's Register Foundation