

SEP -5 1938.

(Received at London Office

REQUEST FOR INSPECTION SERVICES.

DATE Sept. 10th/37.

We confirm our request to the Committee of Lloyd's Register, that they will instruct the Society's Surveyors to furnish their services in connection with three of our Mark 6VQZ Six Cyl. Engines against P/IV.4656 and P/12/9550/1 and which are destined to fill Sales O/No: 37/IV.1894/5/6 for Messrs. Henry Robb Ltd. Leith.

at Lincoln.

and we agree to pay the { fees and expenses } incurred for
{ inclusive charge of } these services.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

NAME OF FIRM

Ruston & Hornsby Limited,

ADDRESS Sheaf Iron Works,

A Hall

Head Buyer

Lincoln.

After signature, please return this form to:—

THE SECRETARY,
LLOYD'S REGISTER OF SHIPPING,
71, FENCHURCH STREET,
LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation