

8.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 185. Port of London
 No. in Reg. Book. Survey held at 50942 on the Wood, Iron or Steel Ferro-concrete: "CRETEGUARD"
 Date, First Survey Last Survey 85 19

TONNAGE — Built at Barrow.
 GROSS 715. Owners Mr. A. J. Vega.
 UNDER DEK 661. Managers
 NET 660. By whom Ferro-concrete Ship Constr. Co. Ltd. When 1919 — 5.
 Owners' Address
 Port belonging to Gijon

Surveyed Afloat or in Dry Dock? Name of Dock
 WB = Cell/D Bor DBa feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the beller space.
 Last Report, No. 83388 Port Low
 CHARACTER, Date of last Survey and of Periodical Surveys. Years assigned now expired. Machinery and Beller Surveys (including date of N.B., if any).
 A1 8.20 DB-519.

Boasting Gr. Britain & Ireland (Except West Coast, Cork to Portland & Firth)
 Continent - from Great to Hamburg.
 Subject to Annual Survey - Experimental Annual Survey - 8.20.
 Society's Freeboard (if assigned) as painted on Ship and now verified.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
 Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Decks	State if Tanks now tested	Engine Room Skylights	Boats
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Outside Plating	Rudder	Hatches	Equipment letter
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Transoms	Windlass	Caulking ditto	Cables (State if now ranged)
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	„ length (on board) size
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	„ Rule length size
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Floors		Ditto ditto at other places ditto	
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting (State if examined.) ditto	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey 1,24,” or “to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptd24, &c.”

Survey Fee (per Section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
 Character Assigned
 Surveyor to Lloyd's Register of Shipping.

