

...the Room  
...Tonnage  
...Crew Space  
...about  
...Engin

1m,12,15.

F.E.

...d by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME *Steel S.S. "ATLANTIC MARU"* Rpt. *Kob* No. *3077*

...e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. *79* Depth "d" *16.0*  
...raming: Table No. *3* Description *Bull angle as approved*  
...ngitudinal No. *30415*  
Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \textit{10.7}$

...ck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the  
...les and the approved plans, and it is submitted she is eligible to  
...classed  $\text{✠}$  *100-A-1. (Steel) "Awwing Deck"* with freeboard," as  
...ommended. The Summer freeboard of *9' 3 1/2"* from centre of disc  
...top of statutory deck line at *Awwing* deck, now marked on the  
...essel's sides, to be inserted in the classification certificate, and  
...orded in the Register Book, and further, the remaining freeboards,  
...shown on the accompanying verification form to be inserted in the  
...ertificate of classification.

*2 Dks (Steel) & Awwing Dk (Steel)*

*Cell DB 327' 1126t, FPT 127t, APT 94t*

*FK. Collision BH to Awwing Dk, 5 BH to Upper Dk, pt. Conn, Av. Cl.*

*Date of Build 2/24*

© 2021 Lloyd's Register Foundation  
See letter 28.4.21  
9.3.21  
H.W.

*It is concluded web frames are fitted on the Sheerstrake Deck as approved for  
...ater vessels but the Surveyors should be requested to state if this is so*

006760-006771-0323