

Subject to the outer plates, post and start (E.W. 36) being specially examined at the next drydocking.

11

28 JAN

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Sh. S. "RUSOILPROD"

Rpt.

Brs

No. 13602

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The *Bristol* Surveyors report this vessel placed in dry dock, bottom cleaned and coated and ~~minor repairs effected~~ *a shoe plate fitted to the after keel plate.*
The E.W. repair to the outer plates examined found in order.
 It is submitted the vessel appears worthy to remain as classed with record of survey 1.37 *subject as above* as recommended.

100A1
 1.37 Brs | Subject re
 Carrying pet in bulk

WAB

[Signature]
 27.1.35

The vessel is being towed to the Black Sea under the Russ
 (see also letter of the 6th inst)



© 2020

Lloyd's Register
Foundation

006819-006830-0065