

Toronto 16

It is concluded that two top end bolts & nuts & two
bottom end bolts & nuts have also been included in the spare
part placed on board in accordance with the Rule requirements
but the Toronto Surveyor should confirm this & also give
the dates of his visits when he examined the completion of
fitting of sea connections, Stern tube, screw shaft & propeller
this has been omitted from his report.

J. J.
29.1.14

Lloyd's Register
Foundation

006819-006830-0228.1