

Rpt. 7.

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19

# Lloyd's Register of Shipping.

(Report on Machinery, No. \_\_\_\_\_ Port \_\_\_\_\_)

## No. 347 ENGINE FORGINGS OR CASTINGS.

I have to report that the ~~Iron or~~ Steel Forgings ~~or~~ Castings, as herein described, manufactured by Eric Forge Co of Eric Pa for the Engines No. 58 being constructed by Collingwood S. B. Co of Collingwood, Ont for the Ship No. 47, being built by \_\_\_\_\_ of \_\_\_\_\_

have been inspected by me as set forth below, and found to be, so far as can be seen, sound

8 crank shaft pieces, one thrust shaft  
one tail shaft

See on Forgings or Castings.

Lloyd's  
No. 347  
A.T.T. 13-12-15

A. T. Thomas

19-12-15

Cleveland, Ohio

	CRANK SHAFT.	STRAIGHT SHAFTING.		
		THRUST SHAFT.	INTERMEDIATE SHAFTS.	PROPELLER SHAFT.
Material	<u>D. H.</u>	<u>D. H.</u>		<u>D. H.</u>
Material made	<u>forged</u>	<u>forged</u>		<u>forged</u>
Dimensions	<u>9 1/8"</u>	<u>9 1/8"</u>		<u>10 1/8"</u>
Process on inspection	<u>black &amp; rough turned</u>	<u>black &amp; rough turned</u>		<u>black &amp; rough turned</u>
Tests on Standard Test Pieces.				
Tensile Test— Tons per square inch	<u>31.5</u>	<u>30.3</u>		<u>31.7</u>
Elongation per cent	<u>29</u>	<u>30</u>		<u>30</u>
Bending Test— Angle before fracture	<u>180°</u>	<u>180°</u>		<u>180°</u>
When Inspected				

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

9 expenses  
Fee (if any chargeable) \$36.00  
To be paid at Cleveland, Ohio



© 2020

Lloyd's Register

If of iron, state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.

000819-000830-0236

Angles on app.			
Spacing	✓ 24	24	