

vessel placed in dry dock, a GENERAL EXAMINATION carried out and notation of "Examined 1. 10. 45"

TELEPHONE: MIDDLESBRO' 43431-2.

MEMORANDUM.

5th November, 1945.

FROM

Lloyd's Register of Shipping,

Lloyds Bank Chambers,

Middlesbrough.

TO

The Secretary,

LONDON.

RECEIVED

7 - NOV 1945

ANSD.....

Dear Sir,

"EMPIRE ANNAN".

With reference to your classing letter of the 2nd instant, it is regretted that the length of cable was reported as 234 fathoms instead of 254 fathoms. It is also regretted that no mention was made in the body of the report in connection with the shell (ss) in way of No.2 hold. This should read:-

Repairs Now effected.

One shell butt in No.2 hold (ss) between 2nd and 3rd frames from after bulkhead, welding found leaking slightly after undocking. A cement box was fitted in way and it is recommended that this be dealt with at first opportunity.

We are, Dear Sir,

Yours faithfully,

The Surveyors, Per:-

J. Nell

006845-006856-0099

16.10.45

m

Referred to Mr. Perrie

108

Noted  
GAM  
8/11/45

R.S.

Middlebrough.

Produce Bank Chambers,

Register of Shipping.

to

MEMORANDUM



© 2021

Lloyd's Register  
Foundation

FROM

RECEIVED BY: MIDDLEBROUGH