

17 APR 1930

No. 85599

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

Port of

NEWCASTLE-ON-TYNE

Survey held at

Date, First Survey

Last Survey

by on the Wood, Iron or Steel

S/S "SIMCOLITE"

(No. of Plates)

2

TONNAGE

1926

Built at

Curzon Hall on Tyne

By whom

Turner S.B. Co.

YEAR

MONTH

When 1930

SS

1465

Owners

Imperial Oil Co.

Owners' Address

(if not already recorded in Appendix to Register Book)

ER DK

1116

Managers

70. B. Elsworth

Port belonging to Montreal

Laid Afloat or in Dry Dock?

Rock Name of Dock

Dry Dock

Destined Voyage?

Cell DBor DBa

feet; uE&B

feet; f

feet

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Capacity tons. FPT tons; APT tons; MT tons. feet tons.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

t Report, No.

Port

Special Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs due to other causes; welds being detailed in the body of the report, should be summarised in the form shown below. Whenever the cement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR

Docking & Completion 1st Entry

Made letter 8th Apr. 1930.

Work done: Vessel placed in dry dock. Bottom cleaned, examined, & recoated.

The Windlass, Steering gear, & Winches Examined under working conditions.

Freeboard Triples 2-3 1/2

TYPE OF DAMAGE REPAIRS:—

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:—

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

CONDITION OF THE

of Decks

Fastenings

Plating

Ribs

Frames

Rivets

Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Dblig. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Greenails

Breasthooks & Stems ditto

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelves ditto

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Feet)

When put on, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length

(on board) size

" Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel in our opinion appears Eligible for the Class Contemplated, and to have record of Survey 4.30

Fee (per Section 39)

Damage or Repair Fee (if any)

Expenses (if chargeable)

Surveyor's Fee (if any)

Fees applied for,

Received by me,

Surveyor's Fee (if any)

Surveyor's Fee (if any)


Committee's Minute

FRI. 25 APR 1930

Character Assigned

See Mdb 3E Rpt 14039

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

006845-006856-0154