

Steamer "AMERICAN TRADER".

On Wednesday, 4th September, 1940, the American
Committee decided to give instructions for the class of
this vessel to be withdrawn from the Register Book and
Three Dots (...) inserted.

9,40

This decision is now submitted for confirmation.

22nd October, 1940.

006857-006867-0140



Please address further
communications on this subject
to THE SECRETARY
and quote the following initial.

R.

Lloyd's Register of Shipping.

71, Fenchurch Street, London, E.C.3

TEMPORARY ADDRESS,

HIGH CLOSE,

WILTSHIRE ROAD,

WOKINGHAM, BERKS.

(TEL. NO. 767.)

Dear Sir ,

With reference to the classification in the Society's Register Book, and to the casualty which is reported to have occurred in the case of the above-named vessel, I beg to acquaint you that the question of inserting a record of the circumstances against the vessel's name in the Register Book will come under the Committee's consideration on the and in the event of such a record being made, the vessel's